

- 1 Lot 1 Model 72260 General International floor drill press with 1HP motor (110V), single-phase operation. Serial number 79171512. Includes operational controls and base stand. Heavy-duty equipment.
- 2 Lot 2 includes an oxygen acetylene hose, gages, and a cart. No tanks are included. Model year, brand name, and specific serial numbers are not visible or provided.
- 3 Lot 3 Milwaukee abrasive chop saw, model 6180-20, Lot 3, serial number 896 C 911430285. Includes base and visible wiring.†
- 4 Lincoln Electric Power MIG 215 wire welder equipped with a Mac track wire drive system and diamond core technology. Serial number U1100406988. Includes cables and attachment components.
- 5 Lot 5 features a Craftsman plastic storage cabinet with dual doors and multiple internal shelves. The cabinet displays signs of wear but remains functional for storage needs.†
- 6 Dayton model 9MRP6 24-inch floor fan.
- 7 Schumacher farm and ranch battery charger designed for 12-volt batteries.†
- 8 Includes 4 jack stands with a 12-ton capacity and 3 jack stands with a 3-ton capacity.†
- 9 OTC 10-ton floor jack, model HDJ 10.
- 10 K Tool International 3-ton capacity floor jack in used condition.
- 11 One-ton capacity hydraulic.
- 12 Strongway engine stand with a 1,000-pound capacity.†
- 13 Yellow Justrite EX safety cabinet with dual doors and adjustable shelves for flammable material storage.†
- 14 Gorilla multi-position ladder with a 300-pound capacity.†
- 15 Max Air floor fan with a large metal frame, protective grill, and integrated wheels for mobility.†
- 16 Generac GP 6500 PowerRush portable generator. Model GP 6500.
- 17 Jobox gang box model 680900R4.
- 18 Morgan bench vise model 45.
- 19 Wilton bench vise.
- 20 Machinist vise.
- 21 Ironton bench grinder.
- 22 Lot 22 2017 Bend Pak model XPR ñ 18 CL, 2 post automotive lift, 18,000 LB capacity, self-contained hydraulics, 14í overall height, 10í between the uprights, very good appearance.

- 23 Lot 23 features a Coats model 4050A tire machine.
- 24 Wheel barrel and yard cart.
- 25 Cabinet featuring a stainless steel top.
- 26 (4) bolt bin organizers containing various contents. Organizers feature multiple compartments for sorting hardware.†
- 27 Lot 27 consists of a grader blade section, confirmed as new.†
- 28 Two shop-built welding tables and one step stool.†
- 29 Large lot, including assorted fasteners, automotive fuses, and miscellaneous parts. Contents stored in bins, boxes, and organizers.†
- 30 Lot 30 features a collection of assorted fasteners, screws, and bolts in multiple sizes and types. Includes organized trays, labeled bins, and boxes sourced from Fastenal and other brands.†
- 31 Collection includes various belts and assorted wire, displayed on a pegboard.†
- 32 Lot 32 steel cabinet featuring a durable stainless steel top and sliding doors.†
- 33 A manual fence post puller, Paragon stake puller, and a blue mechanics creeper.†
- 34 Metal under-mount toolbox with a hinged.
- 35 Under mount toolbox made of metal, red in color. Dimensions of 18 x 18 x 36 inches.†
- 36 Under body storage toolbox measuring 18x24x18 inches.†
- 37 (2) 2-wheel hand carts, Lot 37
- 38 Two 2-wheel hand carts.
- 39 Adjustable steel pedestal table designed as a materials stand.†
- 40 A jack hammer cart along with an assortment of chisels.
- 41 Metal utility cart featuring a flat surface and four wheels for mobility.†
- 42 Milwaukee 2-wheel cart.
- 43 Metal portable scaffold with caster wheels.
- 44 Lot 44 features a variety of assorted fluids and lubricants, including oil, antifreeze, gear lubricants, and other maintenance products.†
- 45 Rigid 6-gallon 3.5 horsepower wet/dry shop vacuum.†

- 46 (1) 20-foot Davidson extension ladder, model D2220-20; (1) Keller fiberglass stepladder with 300 LB capacity; and (1) 2-foot aluminum stepladder/platform stand, 27 inches in height.†
- 47 Lot 47 consists of a manual magnet measuring 5 feet in length.
- 48 Hotsy portable power washer, unable to locate† ID tag, Subaru gas power engine, heater coil needs to be replaced considered cold wash.
- 49 Neuson Rd. 12A gasoline-powered roll compactor roller with serial number 20147828. Features a 36-inch drum width, open operator's platform, and water tank. Hour meter reads 1009 hours. Visible wear present on the seat.†
- 50 2014 Bobcat E50M, serial number AG3N14206, long arm 76 inch length, mechanical quick coupler, hydraulic thumb† hydraulic cylinder is seeping fluid, standard boom, boom swing cylinder is seeping fluid, leveling blade, 16 inch track width, rubber tracks are torn, approximately 1/2 inch of adjustment remaining, final drive sprocket has approximately 50% usage remaining, enclosed cab, radio, 4041 hours on the meter, information display is loose, needs a new battery, Kubota diesel power engine
- 51 Bobcat compact track loader, model MT55, SN B38T11452, rubber tracks have a approximately 30% tread remaining, auxiliary hydraulics, manual quick coupler, general purpose bucket, 1072 hours on the meter, original paint and decal.
- 52 2015 Bobcat skid loader model S750, SN number ATDZ14668, 4300 hours on the meter, tire size 12R16.5 with aggressive, tread pattern, nearly 100% tread remaining, Bob- O- TAC hydraulic, quick coupler, air-conditioning, and heater, radio the throttle control is not operating needs maintenance and servicing, standard auxiliary hydraulics, left rear tire needs air, was used daily during pre-auction preparation needs general maintenance and servicing
- 53 GEHL RT210 Gen. 2 skid loader, SN GHL RT210J00921058, 2447 hours. Features rubber tracks (~30% tread), auxiliary hydraulics, 2 speed, hydraulic quick attach, enclosed cab with radio. Issues: torn seat, loose right armrest, delay in hydraulic release, hydraulic wedge lock maintenance required.
- 54 Virnig land plane with 78-inch width, serial number 109716, equipped with a hydraulic scarifier bar and skid loader quick coupler. Notable surface rusting present.†
- 55 Paladyne fork attachment featuring 48-inch forks.†
- 56 Single fork attachment featuring a trailer hitch ball.†
- 57 Skid loader fork attachment with universal coupler, featuring 36-inch fork length.†
- 58 Bobcat power post hole auger model 15-C, year 2018, serial number 944258992. Features a universal coupler and hex Kelly. Does not include auger bits. Condition is unknown and sold as-is.†
- 59 Bobcat auger bit with a 30-inch diameter and round Kelly design.†
- 60 Auger bit with a 16-inch diameter, featuring a round Kelly attachment.†
- 61 Lot 61 UB impact breaker with an unknown operational condition. Includes an extra bit and features a universal coupler.† Sold as-is without testing.

- 62 Bobcat impact breaker with manufacturer's ID tag not located. Condition remains unknown. Sold as-is.†
- 63 Hydraulic brooms intended for parts. Ideal for salvage or refurbishment.
- 64 Bobcat hydraulic broom Sweepster 72, SN 783703465, with a 6-foot width and universal skid loader coupler. The unit is noted to be non-operational. Blue tag 9137.†
- 65 Heavy-duty skid loader mount coupler plate.
- 66 2017 Allen power buggy model AR16P, SN A16P051708, sells with lender's confirmation, LP fuel, Honda gas engine, purchased new, has not operated for several months. needs a battery, condition is known.† Sells with Owner Confirmation.
- 67 KM International asphalt hotbox model KM8000SX DX C1M1, designed for transporting and maintaining asphalt. Powered by a BECKETT GENIS YS7556 burner using #2 diesel fuel. Features an Allen Bradley PanelView C200 PLC control system. Appears skid-mounted, serial number 1604135 SX DX-8C1M1-13181.
- 68 2022 Crafcro tar kettle model EZ1000SB, SN 1C9ZA1229N1418304. Sells with lender's confirmation, 265 gallon capacity. Features Isuzu diesel power, electronic controls, and a new fan motor.†
- 69 1998 Crafcro E-Z Pour tar kettle with a 200-gallon capacity. Powered by an Isuzu 3-cylinder diesel engine (engine cover removed). Design temperature range is 200–450°F. GVW: 7000 lbs. Mounted on tandem axle carrier with pintle hitch. Signs of significant overflow on the metal shroud; hours of operation unknown.
- 70 Craftco tar kettle model EZ1000SC (2015) with 1000-gallon capacity, tandem axle trailer, adjustable pintle hitch, and Isuzu 3-cylinder diesel engine showing 3540 hours. Non-operational due to a burner issue with a fire hazard. Tires size ST225/75-R15, mounted on a 6-lug rim.
- 71 2011 Craftco tar kettle model EZ 1000 SB with Isuzu diesel power engine. Serial number 1C9 ZA 1227 C 1418007. 4031 hours on meter, non-operational.† Blue tag 9035.
- 72 2011 Craftco tar kettle, model EZ1000SC, serial number 1C9ZN1223C1418008. 1000-gal capacity,† 3-cylinder Isuzu diesel engine,† Non-operational, 4573 hours noted, blue tag 9037.
- 73 Sullivan PALATEK portable air compressor, model D185P1Z4, serial number 19KP000761, sells with lender's confirmation, 889 hours on meter. Features an Isuzu diesel engine, original paint and decal, pintle hitch, and single axle carrier. Left tire is flat.
- 74 Sullivan Palatek DF185P31Z air compressor, SN 102174. 807 hours on meter, powered by Isuzu diesel engine, 185 CFM output. engine operates pressure relief valve shuts down the engine, Missing the exhaust muffler, unit requires maintenance and repairs. Mounted on a single axle with adjustable coupler and pintle hitch, tire size ST175/80P13, 50% tread.
- 75 Sullivan Palatek model DF210P HJD air compressor powered by a John Deere diesel engine. Turbo-charger issues reported, Considered to be non operational, Shows 1029 hours on the meter, control door latch hinge needs repair, and is not mounted on running gear. Serial number 3291.

- 76 2013 Redi Haul trailer model ML5460 S, VIN 47SS091-T6D1026501, 5080 LB GVW, no title bill of sale only, tilt deck trailer designed to transport concrete saws 4 foot 6 inch width and 9 foot 2 inches length, adjustable coupler with ball hitch hydraulic brakes single axle six legrim, tire size ST225/ 75 R 15 30% tread, surface rusting throughout, currently is transporting a Husqvarna power supply model PP3030D Deutz power air cooled engine, unable to find the manufacturer's ID tag, includes powered retractable hydraulic hose, wall saw model 35 H and 1500 H unable to read the manufacturer's ID tag blue tag for the trailer is 9060 and the blue tag for the power supply is 9048
- 77 2007 Redi Haul ML5435 S utility tilt trailer, VIN 47SS091-T-071023243. Features adjustable coupler, pintle hitch, tilt hydraulic deck (9 ft 2 in x 4 ft 6 in), and single axle with ST205/75-R14 tires (50% tread, 1 rim/wheel missing). Includes Husqvarna hydraulic Power Pack w/ Deutz diesel engine (non-operational).
- 78 Wacker Neuson G50 portable generator, 38 kW 48 KVA, powered by a John Deere diesel engine. Mounted on a tandem axle trailer with adjustable coupler and pintle hitch. Features 120/240/480V outputs. Trailer has surface rust and ~30% tire tread. Non-operational with \$10,000 estimated repairs.
- 79 Heavy-duty concrete saw electric type. Condition is unknown.
- 80 Lot number 80 features a Mikasa plate compactor powered by a Honda gas engine.†Condition is unknown.
- 81 Tsurumi portable generator model TPG 4-40 500 HDX. Condition is unknown.†
- 101 2009 International dump truck PayStar 5500I6X4, VIN 1HS XLA HR49-J131056, Eaton automatic transmission, power takeoff, power divider lockout, air brakes, engine brake, speed control, traction control, Cummins ISM 350V red block diesel power engine, 52,000 LB GVW, 12,000 LB front axle, 40,000 LB rear tandem axle capacity, walking beam suspension, pusher axle airlift and steerable, front tire size 11 R 22.5 on steel rims with 100% tread, rear tire size 11 R 22.5 on steel rims with 50% to 90% tread, Davis trailer and truck equipment FMTB ñ 16, serial number Z12007451525442, 16 foot box with straight gate 48 inch side heights with side extension, the bottom of the box is dented, steel fuel tank, single stack, cab is orange in color, dual fuel tanks, new batteries.
- 102 1996 Freightliner dump truck model MEDCONVF L70, VIN 1 FV 6 HFAA 2TL534332, regular cab, 32,000 GVW, 12,000 LB front axle, 20,000 lbs. rear single axle with dual tires, tire size 11 R 22.5 on aluminum rims outside steel rims on the inside, manual transmission, 258,487 miles on the odometer, interiors in fair condition, Cummins 5.9 liter engine, 11 foot steel dump box straight gate, significant rusting on the box, the bottom of the box has severe dents and significant rusting, this truck has not operated for several years, new batteries, needs a starter,† †blue tag number 9002
- 103 22005 International truck tractor, model 86104x2, VIN 1H SHWAH N35J165671, single axle, Eaton Fuller 10 speed air shift manual transmission, driver seat and passenger seat, unable to identify the odometer reading, equipped with Cummins ISM engine, front tire size 11R 22.5 on steel rims, rear tire size 11R 22.5 on steel rims, 12,000 LB front axle, 20,000 LB rear single rear axle, stationary fifth wheel plate, two bag air ride suspension, 151 inch wheelbase, new batteries,† blue tag number 9000.
- 106 2020 Chevy pickup truck model 2500HD VIN 1GC4Y N EY3LF 143242, GVWR 11,350 lbs, 148001 miles on odometer, needs fuel filter, coolant level is low, back camera is broken, service tire monitor system light is on, 4 door Crew Cab, electronic 4 wheel drive, 148,001 mile on the odometer, leather seat covering, 40/20/40 front seats, built in electric trailer brake, DEF solution, exhaust brake, power tailgate,

traction control, OnStar system, steering wheel wrap shows significant wear, Z71 off road package, Duramax diesel engine with Allison automatic transmission, tire size LT275/ 70R18 tires vary from needing to be replaced to 30% tread, power sliding window, 6 foot 8 inch box, tailgate is damaged, Lt. Cab option, dents on the box, red in color.

- 107 2022 Chevrolet pickup truck model 2500 HD, VIN 2GC4YNEY3N1215292, sells with lenders confirmation, GVW 11,350 lbs, 105748 miles on odometer, Tire pressure is low, Coolant level is low, 4 door Crew Cab, cloth interior, 404/20/40 front seats, electronic 4 wheel drive, built in trailer brake, steering wheel wrap is damaged, noticeable signs of usage and cosmetic wear in the cab, Duramax diesel engine, windshield is cracked, 6 foot 10 inch box, tailgate is damaged, Lt. Cab option, cross mount toolbox and auxiliary fuel tank, tires have 20% usage remaining.
- 108 2015 Chevrolet Silverado 2500 HD four-door crew cab pickup truck with VIN 3GCUKSEC7EG400554. Gasoline-powered, equipped with four-wheel drive, driven by a company's supervisor.
- 109 2008 Chevrolet cab and chassis model 3500 HD, VIN 1GC4KYC4GF139356, 204121 miles on odometer, service trailer brake system, coolant system is low, Needs DEF fluid, 4 door Crew Cab, Duramax diesel power engine Allison automatic transmission, cracked windshield, 4 WD shift on the floor, interior shows significant sign of usage fair condition, built in electric trailer brake, automatic transmission, tire size Lt. 235/80R 17, 20% to 30% tread, equipped with an 8 foot 6 inch aluminum flatbed with auxiliary fuel tank, left side mirror is damaged, red in color, needs batteries, † fair condition.
- 110 2012 Chevrolet Silverado 2500HD Z71 with 6.6L Duramax engine. 249,274 miles on odometer, tires are low on air, Notable features include leather seating (driver's seat torn), electronic 4WD, electric trailer brake, spray-on bed liner, and 20% to 30% tire tread. Damage includes severe rusting, dents, door and hood damage, worn interior, and damaged tailgate.
- 111 2017 Chevrolet pickup truck model 2500 HD, VIN 1GC1KWEY2HF115255, 192,094 miles on odometer, Engine power is reduced, coolant level is low, GVW 10,000, 4 door Crew Cab, LTZ cab option, leather seating, driver's seat is tore into the foam, center counsel, electronic 4 wheel drive, steering wheel wrap shows significant usage, interior is in fair condition, Duramax diesel engine, rear tailgate is damaged, dried on concrete, tire size LT265/ 60R 20, 20% tread remaining, red in color, bumper is dented needs maintenance and servicing.
- 112 2012 Chevrolet pickup truck model 2500 HD, VIN 1GC2KXC82BZ314843, 10,000 GVW VIN GC1KYC89BF175393, 150622 miles on odometer, Washer fluid is low, reduced engine power, the original door has been removed, the original door has been removed, a replacement door has been assigned, electronic 4 wheel drive, built in electronic trailer brake, automatic transmission, seat is tore into the foam, leather seat covering, center counsel, bench seat, Duramax 6.6 HD engine with Allison automatic transmission, tire size LT275/70R18 30% tread, 8 foot box which is severely dented and severely damaged, auxiliary toolbox and fuel tank this truck, is considered non-operational, † for a DEF solution problem, tag 9027.
- 113 2012 Chevrolet pickup truck Silverado 2500, VIN 1GC1KYCG2CF229660, 240,539 miles on odometer, Engine light is on, tires are low on air, service park assist, Service traction control, service stabilitrak, 4 door Crew Cab, 4 wheel drive, built in trailer brake, leather seating, driver seats tore into the foam, gasoline power, Z71 package, 6 foot 6 inch box, tire size LT275/ 60R20 needstires to be replaced, needs battery, paint is coming off of the doors, cross mount toolbox, tailgate is damaged, needs maintenance and servicing.

- 114 2015 Chevrolet Silverado pickup model 2500 HD, VIN 1G2CUE85FZ 530796, 10,000 GVW, 134784 miles on odometer, change oil filter and oil, engine reduced power, left door issue, 4 door Crew Cab, 2 wheel drive, built in electric trailer brake, vinyl interior, 40/20/40 front seats, molding on the driver side door is missing, numerous dents in the box and the doors, Duramax diesel engine, Allison automatic transmission, front bumper is dented, 8 foot box, auxiliary fuel tank, tailgate is severely damaged, rear bumper is damaged, tire size LT265/70R18, 30 to 50% tire tread, rims are significantly rusted, back of passenger seat is missing, interior shows signs of significant usage fair to poor condition, truck needs maintenance and servicing.
- 115 2014 Chevrolet pick up truck, VIN 1G0KVC9EF152444, 9500 pound GVW, regular cab, 110,884 miles on odometer, washer fluid low, tires are low on air, four-wheel-drive shift on the floor, gasoline, power engine, built-in electric trailer brake, 40/20/40 seats, cloth interior, manual windows and locks, significant hydraulic oil leak from under the dash on the driver side floorboard, 8 foot box, bedliner, rusting, and dents throughout the entire truck, tire size LT 245/75R 17 with near new tires, front left corner panel severely dented, right rear of the box is severely dented, needs maintenance and service.
- 116 2017 Chevrolet Express box van model G4500 with VIN 1HA6GU CG2HN011498. 70,515 miles on odometer, change oil is needed, low fuel level, Features include a 16-foot aluminum box with a roll-up rear door, automatic transmission, cloth interior, and power windows and locks (non-operational windows). Interior shows wear with torn driver's seat, and it includes a molded plastic water tank and retractable hose reel. Tires vary in condition, sized LT225/75-R16.
- 117 2015 Chevrolet express cargo van model 3500, VIN 1GCZGUCG5F1123928, automatic transmission, power locks power mirrors, 178,000 miles on the odometer, driver's seat is tore into the metal frame, dents throughout the entire body, tire size 245/75R 16, 80% tread remaining, mounted inside of this van is a water tank and power retractable hose, side doors, this was used on the saw crew. is a daily drive driver of a Superintendent. Fair condition needs maintenance and servicing
- 118 2019 Chevy express van model G2500 VIN 1GCWGA FG2K1274362, 8600 LB GVW, 85721 miles on odometer, air is low on tires, automatic transmission, 2 wheel drive, driver seats tore into the foam, gasoline power, † tiresize LT245/75-R16 with 30% tread, mounted inside of this van is a molded water tank with retractable air hose this was set up for a sawing crew, right side sliding door, fair to poor condition. needs servicing and maintenance
- 119 2008 Chevrolet Silverado C3500, VIN 1GB HC34K98 E 216813, 128,582 miles on odometer, needs battery, needs alignment, service air bag, engine light is on, service tire and theft system, 9700 LB GVW, regular cab, automatic transmission, 2 wheel drive, automatic transmission, manual windows, vinyl seat covers, driver's seat is tore into the foam, AM FM CD radio, VORTEC gas power engine, currently the engine is being repaired, tire size LT265/75-R16 with 100% tread, paint is coming off of the cab, equipped with an READING 6 compartment mechanics tool body, the doors are showing significant rusting, center storage, equipped with a air compressor with a Honda GX-200 gas power engine, severe rusting on the right side of the box, overall has fair to good appearance.
- 120 2013 Chevrolet pick up truck, model 2500 HD, VIN 1GC0KXC82DZ109645, 235,598 miles on odometer, needs battery, driver is damaged, low tire pressure, service trailer brake system, 9900 pound, standard cab Duramax 6.6 HD engine with Alison, automatic transmission, truck is considered non-operational, it'll have to be towed, includes auxiliary fuel tank and tool mounted box door is jammed non-operational.

- 123 2016 Chevrolet Silverado 3500 LT, VIN 1 GC 5 KZC 85 GZ 221850, non operational, 4 door Crew Cab, power windows power locks power mirrors, electronic 4 wheel drive, differential lock, electronic trailer brake, traction control, exhaust brake, cloth interior, 40/20/40 front seats foam tore down into the frame, 8 foot box, rear single axle dual tires tire size LT235/ 80 R 17 50% tread, spray on bed liner, auxiliary fuel tank with electric pump and toolbox, Duramax diesel engine and Allison automatic transmission, this truck is considered non-operational, needs an engine, blue tag number 9030.
- 124 2014 Chevrolet pick up truck, VIN1GC1KYEG 3-D F169435, needs engine repaired, can not be driven, four door, crew cab, Z 71 off-road package, vortex, gas, power engine, automatic transmission, electronic four-wheel-drive, captain seating center console, Z 71 off-road package, 6'6" box tire size LT 265/60 yard 20 100% tread, this is considered non-operational needs various engine components, red in color.
- 125 2013 Chevrolet Silverado cab and chassis, model 3500 HD, VIN 1GB3CZC88DF178272, regular cab, Duramax diesel 6.6 HD regular cab, 2 Wheel Dr., 147 inch flatbed with cab guards, single axle of dual tires. This truck is considered non-operational has a DEF solution problem.
- 126 2014 Ram 4500 Heavy Duty crew cab chassis, VIN 3C7WRLFL6EG211115, GVW 16,500 lbs, Cummins diesel engine, automatic transmission, electronic 4WD, trailer tow features, vinyl seats, 136-inch bed with significant rust, recessed ball hitch, dual rear wheels. Non-operational condition.
- 127 Chevrolet pickup truck 2500HD VIN 1 KC 2 KXC 82V Z7314843, no title bill of sale only, 4 door extended cab, Duramax 6.6 HD engine automatic transmission, electronic 4 wheel drive built in electric trailer brake, 5 foot 6 inch box, Z71 off road package, cloth interior, 40/20/40 front seats, driver side door has been removed, this truck is considered non operational, tire size LT285 / 65-R16.
- 128 2012 Chevy pickup truck model Silverado 2500HD, VIN 1GC2KXC82CZ168106, 4 door extended Cab, automatic transmission, electronic 4 wheel drive, built in electronic trailer brake, tow haul mode, cloth interior, 6'6" box with insert bed liner, crossmount toolbox, auxiliary fuel tank with pump, severe rusting over the wheel wells, tire size LT275/ 70R18 with 70% tread, this truck is considered non-operational blue tag number 9028 company number P25, driver side door frame has been damaged.
- 129 2007 Chevrolet 2500 VIN 1GCHK29677E596513, 4 door super cab, electronic 4 wheel drive, built in electronic trailer brake, automatic transmission, center console, vinyl interior, rear bench seat, Duramax diesel engine, Allison automatic transmission the driver side door has been removed, Z71 off road package, severe rust over the wheel walls, tire size LT265/ 70R17 20% tread, this truck is considered non-operational tailgate has been removed and is severely damaged, blue tag of 9029.
- 130 2011 Dodge Ram cab and chassis model 4500 ST VIN 3D6WE6EL1BG579271, regular cab, cloth seat covering, 4-wheel drive shift on the floor, automatic transmission, windshield is cracked, Cummins diesel power engine, rear single axle with dual tires, tiresize 225/ 70 R 19.5 with 50% tread, interior is in poor condition, this truck is considered non-operational, cab and chassis only blue tag number 9008.
- 134 2010 Mustang utility trailer model GF15K27, VIN1C9GF2727A S 843001, 8 foot deck width 22 foot deck length with five foot Beaver tail and ramps, has concrete saw ramps in addition to standard wheel ramps, side pockets, fifth wheel hitch ball type, 30,000 LB GVW, tandem axle with dual tires tire size 215/ 75 R 17.5 with 50% tread, front left wheel seal is leaking, rims have dried concrete in the rims, spring suspension, wood decks in fair condition, double landing jacks, was purchased new, has fair appearance.heel seal, and fair wood deck condition.

- 135 2015 CRONKITE dump trailer model CDT 14-14K, VIN473DB1920F-1000250, 6'8" by 14' by 28" sides, dump trailer bottom of the trailer is significantly dented and signs of usage, adjustable coupler with pintle hitch, tandem axle with eight leg rim, tire size ST235/ 80 R 1650% tread, rear swinging gates, surface rusting throughout, trailer number T-24 blue tag 9069. Needs a battery.
- 136 2012 MIDSOTA dump trailer model VERSA dump HV-14, VIN 1M9AD142XCA633319, 6'10" width 14' length 24 inch height, adjustable coupler with pintle hitch, needs a battery, includes a tarp, tandem axle with eight leg rim, tire size ST235/ 80R16 has swinging gates, ramps, appears to be in fair condition.
- 137 2015 Big Tex model 14 dump trailer, VIN-16 VDX 1420 F 5003754, 14,000 LB GVW, 6 foot 11 inch width by 14 foot length and 24 inch side heights, tandem axle with eight lug rim, tire size ST235/ 85-R16 with 50% tread, the floor bed shows significant dense and wear rear side gates, D ring, does not have a tarp, electric brakes single landing Jack, needs a battery, surface rusting throughout. Company number T34 blue tag 9070
- 138 Empty
- 139 2016 Pace American enclosed van trailer, model JV7X16TE2, VIN 53BPTEA25H030038. Features 7 ft width, 16 ft length, tandem axle, non-riveted side, five-lug rims, ST205/75R 15 tires (50% tread), V-nose, ball hitch, side door, rear fold-down door, and SE Journey series design, white exterior.
- 140 2017 Pace American enclosed utility trailer, model JV85X20 TE 3 Journey SE series, VIN 5 3BP T EB21HA027555, 8 1/2 foot width, 20 foot length, tandem axle, tire size ST225/ 75-R15 on a 6 lug rim, V nose, ball hitch, electric brakes, side door and rear fold down door, non-riveted sides, aluminum diamond plate rock guards, rear fold down door this trailer has severe damage on their fold down gate right rear corner on the left side exterior has indications of significant usage appears to be in fair condition.
- 141 2000 S&S enclosed van trailer, VIN SS0600ECT19372854, 7000 LB GVW, adjustable coupler with ball hitch, electric brakes, 5 lug rim, tire size ST205/ 75-R15 with 50% tread, side door and rear fold down door, non-riveted sides, 6 foot 6 inches width 16 foot length, 88" height, placard with the company's name, significant light rusting on the rear right corner, flat front, equipped with side compartment, side door is damaged this fair appearance rear fold down door is damaged appears to be in fair condition.
- 142 Enclosed van trailer, no title bill of sale only, tandem axle tire size ST225/ 75-R15 on five lug rim, tires with 50% tread, 7 foot 4 inches width 14 foot length, adjustable coupler with ball hitch, electric brakes, rear fold down door, interior heights 88 inches, interior has paneling has significant yellow and white overspray sprayed on the walls, equipped with an electric breaker box conduit and wiring, unable to find a manufacturer's ID tag, riveted sides side door has company brand name placard on the sides of the trailer, fair appearance fair condition. Blue tag 9075
- 143 Hotsy portable power washer model 1280SS, serial number 11105580-163230, Rating when NEW 3500 psi, 5.1 gallons per minute, 2.72GPH, 12 VDC, does not heat cold water only, Honda engine.
- 144 Utility trailer, 6 foot 6 inches width 14 foot length with three foot Beaver tail and fold up ramps, tandem axle six leg rim, tire size ST225/ 75-R15 steel rims 50% tread, wood decks in fair condition fenders are rusted through, paint has come off most of the frame significant surface rusting, also includes a 925 gallon Rotary mold water storage tank with horizontal support legs and tie down hoops, does not manufacturer's tag, †

- 145 Cronkite utility trailer, tandem axle, adjustable coupler with pencil hitch, manufacturers ID tag cannot be read, fold up ramps, includes the Northstar power washer and 525 gallon molded plastic tank, considered to be used as a portable wash trailer, six lug rim, size ST225/75R 15
- 146 2011 Cronkite utility trailer model 2600 EWA, VIN 473262028B1000120, 6'8", 16' length, fold up ramps, adjustable coupler with ball hitch, electric brakes, tandem axle, six lug rim, tire size ST225/75-R15 with 50% tread, paint's wore off most of the areas wood decks in fair condition currently used to transport a concrete saw. Includes 525 gallon molded plastic tank.
- 147 Cronkhite utility trailer, tandem axle, includes (2) plastic tanks 550gal each, 16 foot deck, fold up ramps, six lug rim, tire size ST225/75R 1550%, adjustable couple of pencil hitch, surface rusting, fair condition
- 148 2014 CRONKHITE utility trailer, model 5110 EA, VIN 473522624E 000250, 15,500 GVW, deck over design, adjustable coupler with pintel hitch, electric brakes, manual landing jack, tandem axle tires, tire size ST235/80R16, 8 lug rim with 50% tread, deck is 8 foot width 16 foot length with 5' Beaver tail and fold up ramps, side pockets, wood deck, has several boards it should be replaced, the other boards are showing weathering, paints removed in most of the area, has fair appearance, fair condition. blue tag number 9059 company number T-23.
- 149 2008 Trailer Man cargo trailer model CST7162-S12, VIN 5L3CX18256L000696, adjustable coupler with ball hitch, single landing Jack, electric brakes, 6'10" width, 16' deck with 2' beaver tail and fold up ramps, tandem axle with eight lug rim, tire size LT235/85 R 100% tread, fenders are damaged, was used to transport concrete saws, fair appearance.
- 150 16' wooden deck, adjustable coupler, tandem axle, includes dimensional lumber. Buyer must include the contents with the purchase.†
- 151 14-foot bed, no title bill of sale, 3-foot beaver tail, tandem axle, surface rust, unused for years. Includes the items found on the trailer.† Buyer must include the contents in the purchase.†
- 152 2006 Utility saw trailer VIN 47SS091-T271023244, model ML5435 S, no title bill of sale, 3500 LB GVW, 4 foot 6 inches width 9 foot 2 inches length, single axle, full down ramp, tilt bed, adjustable coupler with ball hitch, hydraulic brakes, severe rusting on the fenders, this is designed to haul a concrete saw significant rusting does have a manufacturer's ID tag uncertain if the brakes are functioning tire size ST225/75 R 1550% tread surface, fair appearance.
- 153 2012 CRONKHITE utility trailer, VIN 47311161431000183, tandem axle, 6'2" width and 12' length, missing 2 rims and tires, ball hitch with adjustable coupler, electric brakes, sidewall measures 30 inches, significant rusty, missing a rear swinging gates considered to be non-operational. Missing one rim and wheel on each side.
- 154 2015 Cronkite utility trailer, model M-ut-12EA, VIN 473111611G1000020, 7'x12', 30" sides, tandem axle, adjustable coupler with ball hitch. The channel frame tongue has been reinforced.
- 155 CRONKHITE utility trailer, unable to find the manufacturer's identification manufacturer's tag,- no title bill of sale only, tilt deck, 76 inches width, 12' length, single axle, 5 lug rim, tire size ST225/75-R1475R14, wood deck, wood deck with expanded metal, paint is wore off. blue tag number 9057 will need to verify for registration, license plate number LS7708N.

- 156 REDI HAUL, 9'6" deck, VIN 47SS091THG1028044, new in 2016, no title bill of sale only, single axle was six lug rim, tire size ST225/75R 15, fold down gate, adjustable coupler with ball hitch, tilting deck, used to transport a concrete saw.
- 157 2012 Redi Haul trailer, VIN 47SS091T5C1025791, fold down gate, ball hitch, no title bill of sale only.
- 160 Custom built curb saw featuring a Duetz air-cooled diesel engine, self-contained hydraulics, hydraulic horizontal positioning for a 24-inch saw blade capacity, self-propelled with hydraulic transmission. Includes blue tag 9082. Hydraulic motor is missing.
- 161 2023 Lissmac Multicut 605 SG concrete saw, serial number 054812, sells with lender confirmation, powered by a 55 kW Hatz 4H50TI CD diesel engine with 280 hours. Needs locking ring on new front right wheel, Features 1200mm blade capacity, emission control engine, and is operational. Replacement wheels are included.† Blue tag 9085 included.
- 162 Husqvarna concrete saw, model FS 6610 D T3-3-SPD 26?, 1863 hours on meter, John Deere engine, operational, SN 0012850697001.
- 163 Husqvarna FS 7000 D concrete saw might be out of fuel, unable to start, Forward and reverse won't operate might need a cable, with a rechargeable battery. The battery requires charging. Sold as-is, with visible signs of prior use.
- 164 Dimas concrete saw FS8400 SN 000000432115, 1251 hours on the meter, John Deere diesel the display is very difficult to read, (4) blades 54", 43", 42.5", 38.5" and 36" are included.
- 165 Husqvarna concrete saw, Model FS6600DD T3-3 SPD36?, SN 001301912001, needs battery, need right wheel bearing, reported to be operational, needs a new front wheel, company number C62, blue tag 9085.
- 166 2012 Husqvarna concrete saw model FS-6600D-T3-30 inch, serial number 00130181500, will start, won't go up & down, will traverse forward & reverse, John Deere diesel power engine, 30 inch diameter blade capacity, Display is difficult to view, 2305 hours on the meter, missing engine covers, radiator needs cleaning, reported to be operational. Blue tag 9094.
- 167 Husqvarna FS7000D concrete saw offered for parts only. Serial number is not readable. Features a blue tag number 9092. Sold as-is with visible wear, missing components, and no operational.
- 168 Husqvarna concrete saw model FS 4800D. Non-operational, requiring hydraulic and gauges repair. This unit does not travel. Blue tag number 9093. Sold as-is for parts or repair.
- 169 Davana FS 4800 D concrete saw, non-operational and sold for parts only. Blue tag number 9096. Includes visible exterior components and internal mechanisms. Condition is as-is; repairs or part extraction may be required.
- 170 Husqvarna FS 4800 D concrete saw, labeled with blue tag number 9090. Sold as non-operational for parts only.†
- 171 Husqvarna FS 5000 D concrete saw, noted as non-parts only.†

- 172 Non-operational Husqvarna FS 4800 D concrete saw offered for parts only. Includes blue tag number 9086.†
- 173 Husqvarna concrete saw model FS 7000 D, listed as non-operational.†
- 174 Dimas concrete saw model FS 4800 D with blue tag number 9099. The saw is non-operational and requires hydraulic work. Includes gauges. Sold as-is, with visible wear from prior use.
- 175 Diamond Products electric concrete saw powered by a 30 HP Baldor motor, 230/460 V, three-phase. Serial number 156732, marked with blue tag 9098. Condition is unknown.
- 176 Husqvarna concrete saw model FS 6600 D, T 3ñ3,† serial number 00131405601. Offered for parts only and is not operational.
- 177 Husqvarna concrete saw sold as non-operational and for parts only. Includes blue tag number 089. This unit is intended for salvage or repair purposes and is not in working condition.
- 178 Husqvarna concrete saw model FS400LV, serial number 2018ñ2000170 equipped with a Honda gas engine, Unit shows signs of wear consistent with prior use.
- 179 Diamond products, electric power, concrete saw equipped serial number 140620. Appears in used condition with visible signs of wear.
- 180 2023 Diamond Products concrete saw model CC113H-XL14 Buckshot with serial number 170447, sells with confirmation by lender, powered by a Honda gas engine. The saw does not include a belt guard but comes with a diamond blade. Operational condition.
- 181 Edco concrete grinder model CPM-8-9H, SN 140410142, SKU 79300, featuring a gas-powered engine.
- 182 (2) 16î Core drill bits, requires a 2 inch and 2 1/2 inch lug wrench.
- 183 18î Large core drill bits. Require different size lug wrenches.
- 184 24î Large steel core drill bit.
- 185 12î Industrial-grade core drill bits.
- 186 14î Core drill bits.
- 187 10î Core drill bits in assorted sizes.
- 188 Lot 188 six core drill bits size is vary 7 inches and 8 inches.
- 189 Lot 189 6 inch core drill bits
- 190 Lot 191 core drill bits various sizes ranging from 3 3/4" up to 6".
- 191 Core drill bits in various sizes.
- 192 Core drill bits, various sizes ranging from one and 1/2 inch up to three and three-quarter inch

- 193 Bit extensions.
- 194 (6) Several heavy-duty core drill bases.
- 195 (2) Hilti core drills with bases. The condition of the items is unknown.†
- 196 (2) core drill bases.
- 197 Core Bore CB30 hydraulic power unit. Overall condition is unknown and has not been tested.†
- 198 Husqvarna electric power saws, including a ring saw and chain saw, along with associated controls and cables. Cord drill, PP 60 condition unknown
- 199 Partner K3600 hydraulic ring saw, Condition appears used, with visible wear. Functional status unverified, sold as is.
- 200 2023 Castors Wolverine Hydraulic wall saw model WFC-20D-15GPM, SN 2626, sells with lenders confirmation, attached hoses, 20 inch diameter, diamond blade, purchased as new.
- 201 Diamond Products hydraulic concrete saw equipped with a diamond blade. Serial number 14 15. Condition is unknown.
- 202 ICS hydraulic chain saw, 25 segment chain model is unknown includes tool bars, condition is unknown.
- 203 ICS Hydraulic chainsaw, model unknown. †Condition unknown.
- 205 Lot 205 quantity of 3WEKA electric core drills condition unknown.
- 206 Husqvarna electric demolition saw, condition is unknown.
- 210 Wall saw guards, featuring various sizes, types, and conditions.†
- 211 Wall saw track and attachments. Components are assorted in size and functionality. Condition varies.
- 217 (2) Jack hammers, (1) chipping hammer, Sold as-is.
- 218 Lot 218 includes a pallet with a variety of tools and items such as brooms, hot asphalt wipes, concrete tools, rakes, and general miscellaneous equipment. Items are in mixed used condition, ideal for construction or maintenance purposes.
- 219 Lot 219 includes an assorted collection of tools such as post drivers, scrapers, and sledgehammers.†
- 220 Lot 220 includes assorted brooms, handle extensions, and concrete rakes.†
- 221 Shovels and scoops arranged on a wooden pallet.†
- 223 Lot 223 assorted drop cords in various sizes and conditions.†
- 224 Lot 224 consisting of assorted trailer hitches and related accessories.†

- 225 Lot 225 includes assorted tiedown straps of various conditions, sizes, and types.†
- 226 An assortment of pry bars and pick hammers.
- 227 Log chains, including various types and lengths.†
- 228 Lot 228 contains assorted starters and alternators.†
- 229 Chain binders and chains.
- 230 Assorted lot.
- 231 A variety of drywall and paint tools.
- 232 Lot 232 is an assorted collection of paint aerosols, oils, and mixed maintenance supplies.
- 233 Lot 233 consists of an assorted collection of filters in various sizes, types, and brands.†
- 235 (6) Scaffold ends, assorted braces, and four aluminum scaffold planks.†
- 236 Concrete tools, including bull floats, poles, straight edges, and rerod chairs.† Lot number 236.
- 237 Lot 237 includes an assorted mixed lot of air, hydraulic, and water hoses.†
- 238 Lot 238 contains an assortment of water hoses in various sizes, types, and conditions.†
- 239 Lot 239 includes a variety of air hoses of different lengths and sizes.†
- 240 Gasoline cans in various conditions, some dented.
- 241 Diesel fuel cans, mostly Justrite brand, condition unknown.
- 242 Lot 242 Various sizes and types of concrete saw guards, on pallet.
- 243 Lot 243 Quantity of assorted concrete saw guards in various sizes and types.
- 244 Lot number 244 featuring Craftco hot applied modified asphalt sealant. Includes new 30-pound boxes.
- 245 Lot 245 (4) Pallets of assorted diamond saw blades in various sizes and conditions.
- 246 Lot #246 includes concrete saw guards in various sizes and types.
- 247 Lot 247 Various sizes and types, many need re-tipping or are unusable.
- 248 Lot #248 includes various sizes and conditions of discharge hoses.
- 249 Airport runway stencils with yellow material included.
- 250 Approximately 250 form stakes and rebar bars.

- 251 Lot 251 contains hydraulic power units, saws, and related items.
- 252 Black Diamond abrasive coal slag in multiple bags. Suitable for blasting.
- 253 Pallet containing multipurpose sand and Sicca Crete.
- 254 Includes 50 and 100 gallon tanks; condition unknown, exposure to rain noted.
- 255 50 amp, 480 Volt, three-phase drop cord, 6 AWG gauge, for generator use.
- 276 Backer rod in multiple sizes, types, and quantities. Located off-site.
- 277 Burlap and concrete blankets; quantity and conditions unknown.
- 278 (4) molded plastic tanks: 225 and 125 gallon sizes, various conditions.
- 279 Molded plastic tank with a flat bottom, offering a 4,500-gallon capacity. Currently stored indoors.
- 280 525-gallon plastic tank with tie down bars, no lid, molded design.
- 281 (3)† mold flat bottom storage tanks; likely plastic material.
- 282 (4) molded plastic tanks including 225-gallon and 125-gallon sizes.
- 283 Includes two KM asphalt recyclers from 2016 with cracked displays, condition unknown.
- 285 Steel frame rack with a sturdy design, labeled Lot #285.
- 286 Includes six sturdy precast concrete blocks for various uses.
- 287 Wooden storage box with hinged door and metal support brackets.
- 288 Cut-off sections of black corrugated drainage pipe.
- 289 Safety cones and TRAFFIX Little Buster sign stands.
- 290 Includes various types and sizes like C61 Checkmate, GRACOTEXSPRA sprayer, and epoxy pump.
- 291 Non-operational items: concrete saws, power washers, blower, frames.
- 292 Non-functional water pumps with Honda engines.
- 293 Includes steel-framed traffic signs and rolls of plastic barrier fencing.
- 294 Includes 6 uprights, 12 bars, and shelves; teardrop adjustable, disassembled.
- 295 Includes generators, water pump, grinder, and impact hammer.
- 296 STIHL demolition saws and blower packs in non-working condition.

- 300 Includes two DeWalt DWE4517 grinders, one Hilty DG 150 grinder, and accessories.
- 301 Adjustable clamps and C clamps.†
- 302 Four aluminum pipe wrenches in varying sizes.†
- 303 Lot 303 includes four cast iron pipe wrenches.†
- 304 Cast iron pipe wrenches in varying sizes and designs.†
- 305 Lot 305 includes a collection of assorted adjustable wrenches†
- 306 Two cast iron pipe wrenches measuring 36 inches and 48 inches.†
- 307 Sledge hammers and rubber mauls featuring various sizes and designs.
- 308 Sockets, ratchet wrench, and extensions.
- 309 Sockets in a plastic case, various sizes and types.†
- 310 Sockets and related tools†
- 311 Breaker bars and a ratchet.†
- 312 Lot 312 includes assorted hand tools.
- 313 Lot 313 includes vise grips in used condition.†
- 314 Lot 314 includes an assortment of combination wrenches in various sizes and types.†
- 315 Lot 315 includes an assortment of combination wrenches in various sizes, types, and styles.†
- 316 Wrenches in varying sizes and conditions.
- 317 Wrenches of various types and sizes,†
- 318 Lot contains an assortment of masonry drill bits in various sizes.†
- 319 Screwdrivers in varying sizes and types.†
- 320 Lot 320 includes assorted files and hand tools.
- 321 Lot 321 features assorted hammers in various types and sizes.†
- 322 Lot 322 features a collection of assorted pry bars in varying sizes, conditions, and finishes.†
- 323 Lot 323 includes a mixed lot of clevis pins, trailer receiver locks, and related items.†
- 324 Multiple hammer drills,†

- 325 Bosch rotary hammer tool in used condition.†
- 326 Corded drills with attached stirrer attachments.†
- 327 Lot 327 assorted wheel measurers†
- 328 Lot 328 includes an assortment of corded tools comprising grinders and saws.†
- 329 Portable ventilator fan†
- 330 Lot 330 †2 Tsurumi submersible water pumps.
- 331 Corded heat guns.
- 332 (2) corded hammer drills.
- 333 Lot 333 features a mixed set of tools, including taps, dies, and Allen wrenches organized in red carrying cases.†
- 334 Lot featuring saws and squares, including handsaws, hacksaws, and a framing square,
- 335 Bolt cutters and crimpers.
- 336 Lot 336 includes a collection of assorted levels in various sizes and brands.
- 337 Lot 337 includes three pry bars of varying sizes and a large wrench.†
- 338 Tire wrenches and related items, including multiple tools and rods.†
- 339 Red cargo net made of durable straps, includes multiple metal hooks
- 340 First aid kits and safety helmets. The safety helmets are red, with visible wear.
- 341 Chalk lines, primarily chalk containers, gloves, and additional accessories, including a reel of string.
- 342 Collection includes various metal and plastic traffic signs such as "Stop", "Do Not Enter", "Road Closed", along with stencils for lettering including "Office" and "Parking".†
- 343 Lot 343 contains an assortment of abrasive cut-off wheels in various sizes, types, and conditions.
- 344 Lot 344 comprises an assorted collection of manual caulk guns in various styles and conditions.†
- 345 Lot 345 includes assorted heaters of various types.†
- 346 Lot 364 (6) concrete sprayer cans.
- 347 Lot 347, a bracket mount designed for attaching a snow plow to a pickup.†
- 348 Lot 348 comprises a collection of replacement wheels for concrete saws,†

- 349 Lot 349 contains an assorted collection of safety belts and fall protection devices.†
- 350 Lot 350 containing a selection of hard hats, protective rain gear in various colors, high-visibility jackets, and work boots.
- 351 Water Container
- 352 Grease guns in various conditions.†
- 353 Concrete finishing tools, including trowels, floats, brushes, and edging tools.†
- 354 Lot 354 includes assorted utility items.
- 355 Jumper cables showing various use.†
- 356 Various sets of gear pullers. Items are metal and in used condition, suitable for automotive or mechanical applications. Contents are contained within a crate.
- 357 Rolls of shrink wrap and a collection of zip ties.†
- 358 Water wands used for power washing.†
- 360 Large lot consisting of approximately 16 lineal feet of assorted items. Includes various tools, hardware, safety gear, and miscellaneous equipment. Items are sold as a single lot and may vary in condition.†